

. JFK. (old model)

06/01

MB3712 transistor replacement with new Low Frequency Amplifier Pcb. Ass'y

- 1- Remove 2x MB3712
2. Drill the heatsink and screw the Pcb. Ass'y t/w the wedge.
3. Connect the Pcb. Ass'y and apply modifications as following:

