





DESIGN	DRAWN BY	UNIDEN No.	MODEL No.
29MAR2006	25APL2006	UB347ZH	UBC3500XLT
KOBA I	KOBA I	TITLE MAIN ASSY	
CHECK. BY	APPRO. BY	SCHEMATIC DIAGRAM	
2006JUL26		DRAWING No.	
KODA		E 12-****	
REV. No.		UNIDEN CORP.	




Use Pb free Solder


B101: PH-309CA MAIN PCB TOP VIEW

PARTS DIRECTION


IC111




IC103




IC114




Q11



IC104




FT104



FT 103

NON DIRECTION
NON UP AND DOWN

SHIELD CASE




*1: NJ LOCK GREEN

DESIGN. BY	DRAWN. BY	UNIDEN NO.	MODEL NO.
KODA		UB347ZH	UBC3500XLT
2006APR26	2006APR27	TITLE MAIN ASSY (1/2)	
CHECK. BY	APPRO. BY	CHIP LAYOUT TOP VIEW	
		DRAWING NO.	
		E23-*****	
REV. NO.		UNIDEN CORP.	

B101: PH-309CA MAIN PCB BOTTM VIEW

Use Pb free Solder

PARTS DIRECTION



Q2




Q3




FT101




FT102




Q11




Q29





Q31



IC102




IC106



SOLDERING


*1: PCB AND SHIELD CASE

DESIGN. BY	DRAWN. BY	UNIDEN NO.	MODEL NO.
KODA		UB347ZH	UBC3500XLT
2006APR26	2006APR27	TITLE MAIN ASSY (1/2)	
CHECK. BY	APPRO. BY	CHIP LAYOUT BOTTOM VIEW	
		DRAWING NO.	
		E23-*****	
REV. NO.		UNIDEN CORP.	




*1: DP401 MANUAL SOLDERING

B401 PH-310BA (2/2) [TOP VIEW]



JIG PCB



HOLDER: DISPLAY
GHDZ4B9814Z

* DP401

INSULATION PLATE
RZEB4C0408Z

SORDERING : MANUAL

PCB

REFLECTION SHEET
RETC4C0805Z

REFLECTION SHEET
RETC4C0407Z

REFLECTION SHEET
RETC4C0806Z

* DP401 : Remove protection sheets both side befor soldering to PCB

DESIGN. BY	DRAWN. BY	UNIDEN NO.	MODEL NO.
KODA	KODA	UB-347ZH	UBC3500XLT
2005JUN15(2005PR2)			
CHECK. BY	APPRD. BY	TITLE	KEY ASSY (1/2)
	APPRD. BY	CHIP LAYOUT TOP VIEW	
		DRAWING NO.	E23-25055
REV. NO.	UNIDEN CORP.		

(IT'S NOT NEEDED FOR MASS PRODUCTION.)

