


Wagner Mod. 309

(1)



1. 50V 5.0V 1.0V 0.5V
2. 50V 5.0V 1.0V 0.5V
3. 50V 5.0V 1.0V 0.5V
4. 50V 5.0V 1.0V 0.5V
5. 50V 5.0V 1.0V 0.5V

1. 50V 5.0V 1.0V 0.5V
2. 50V 5.0V 1.0V 0.5V
3. 50V 5.0V 1.0V 0.5V
4. 50V 5.0V 1.0V 0.5V
5. 50V 5.0V 1.0V 0.5V

1. 50V 5.0V 1.0V 0.5V
2. 50V 5.0V 1.0V 0.5V
3. 50V 5.0V 1.0V 0.5V
4. 50V 5.0V 1.0V 0.5V
5. 50V 5.0V 1.0V 0.5V

1. 50V 5.0V 1.0V 0.5V
2. 50V 5.0V 1.0V 0.5V
3. 50V 5.0V 1.0V 0.5V
4. 50V 5.0V 1.0V 0.5V
5. 50V 5.0V 1.0V 0.5V

1. 50V 5.0V 1.0V 0.5V
2. 50V 5.0V 1.0V 0.5V
3. 50V 5.0V 1.0V 0.5V
4. 50V 5.0V 1.0V 0.5V
5. 50V 5.0V 1.0V 0.5V